


## Brake Cable

### PBK-JE18-XX




Motor Side		Drive Side	
Pin	Signal	Signal	
1	B1	B1	
2	B2	B2	

#### Motor Side Connector

Crimping  
Contact(Hole)

CGRSB-2BMFA-SL8001

A View From  
Pins Press-in  
Side



## Connection Cable

### EtherCAT Connection Cable PSC-DR0A-0M3



### ESView Debugging Cable USB-RS485 (RJ45)



### ESView Debugging Cable (EtherCAT) MINI USB-Double Magnetic Ring Shield-1M5

