

# 04

# ACCESSORIES

## Cables

### Power Cables

#### PDM-JB18-XX



Motor-side Connector




Pin No.	Signal
1	U
2	V
3	W
4	FG

Drive-side Connector



Pin No.	Signal
1	U
2	V
3	W
Crimp Terminal	FG

#### PDMB-JB18-XX



Motor-side Connector



Pin No.	Signal
1	U
2	V
3	W
4	FG
5	B1
6	B2

Drive-side Connector




Pin No.	Signal
1	U
2	V
3	W
Crimp Terminal	FG
5	B1
6	B2

#### PDM-GA14-XX- II




Motor-side Connector



Pin No.	Signal
B	U
I	V
F	W
C	FG
D	FG


Drive-side Connector




Pin No.	Signal
1	U
2	V
3	W
Crimp Terminal	FG

Shorting Stub, Cable BVR1.5mm<sup>2</sup>[BLACK]

#### PDMB-GA14-XX- II




Motor-side Connector



Pin No.	Signal
B	U
I	V
F	W
C	FG
D	FG
G	B1
H	B2

Drive-side Connector




Pin No.	Signal
1	U
2	V
3	W
Crimp Terminal	FG
	B1
	B2

Shorting Stub, Cable BVR1.5m


## PDM-GD14-XX



Motor-side Connector




Drive-side Connector




Pin No.	Signal
A	U
B	V
C	W
D	FG

Pin No.	Signal
1	U
2	V
3	W
Crimp Terminal	FG

## PDM-GD12-XX




Motor-side Connector



Pin No.	Signal
A	U
B	V
C	W
D	FG

Crimp Terminal	Signal
Crimp Terminal	U
Crimp Terminal	V
Crimp Terminal	W
Crimp Terminal	FG


## PDM-JE18-XX



Motor-side Connector



Drive-side Connector



Pin No.	Signal
1	U
2	V
3	W
4	FG

Pin No.	Signal
1	U
2	V
3	W
Crimp Terminal	FG